

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

582
North
1/2-1
0.878 mi.
4638 ft.

MARLBORO HOUSES
2257 W 11TH ST, BLDG 13
BROOKLYN, NY

NY Spills **S111317252**
N/A

Relative:
Higher

Actual:
12 ft.

SPILLS:

Name: MARLBORO HOUSES
Address: 2257 W 11TH ST, BLDG 13
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1108230 / 2011-09-28
Facility ID: 1108230
Facility Type: ER
DER Facility ID: 410517
Site ID: 455950
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C4
SWIS: 2401
Spill Date: 2011-09-27
Investigator: RVKETANI
Referred To: Not reported
Reported to Dept: 2011-09-28
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-09-28
Spill Record Last Update: 2011-09-28
Spiller Name: KEITH
Spiller Company: MARLBORO HOUSES
Spiller Address: 2257 W 11TH ST,BLDG 13
Spiller Company: 999
Contact Name: KEITH
DEC Memo: "09/28/11- Keith Williams from DEP- Industrial Waste (347)672-6075 said he went to the site. Wastewater mixed with waste oil is coming out from the building into a grassy area. 9/28/11 - Raphael Ketani. I made an unannounced site inspection. I went to the area containing the building at 2257 West 11th Street, Brooklyn. This building is one of many 6 story or higher red brick buildings in a large public housing project called the Marlboro Houses. I went to the back of the building. Once there, I saw a small, wheel mounted water pump that was pumping what appeared to be water onto the macadam pavement next to the back of the building. I also saw small pools of black liquid on the lawn across the paved area from the building. The liquid on the macadam pavement looked black and had a slight sewage odor. The suction hose to the pump extended down into a stairwell. After a while, a man appeared from the stairwell. He said that he was the super for the building. His name was Mr. Iganacio(?). He said that a sewage line had broken in the basement of the building. I asked him whether the building used oil. He said that it was heated by steam. I viewed the stairwell and it appeared as if there was 4 feet or more of water in the stairwell and the basement. I asked him to take me to the management office. At the management office, I met Ms. German,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Remarks:

the superintendent for all of the buildings at Marlboro Houses. She said that the problem was a broken or plugged sewer line, but not oil. I thanked her for the information, and I left the site. As the spill was essentially sewage, and as the NYC DEP inspector had already been to see the site, I determined that this incident was not the jurisdiction of the Spills Unit. So I closed the spill case. "
"steady ongoing discharge of waste water mixed with oil being pumped out onto grassy area outside building"

All Materials:

Site ID: 455950
Operable Unit ID: 1206100
Operable Unit: 01
Material ID: 2203111
Material Code: 0060A
Material Name: wastewater
Case No.: Not reported
Material FA: Other
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported